

SOW CHANGE PROPOSAL

SOW-02-832-1-09999A-2/4

Change 3

3 December 2001

STATEMENT OF WORK (SOW)
for the
Inspection and Repair Only As Necessary (IROAN)
of the
Mobile Electronic Warfare Support System
NSN 5865-01-236-4235

SOW Control Number SOW-02-832-1-09999A-2/4 Change 3

Change Paragraph 3.3.2.5.2 from:

In the event that plate replacement is necessary, only Luken Steel or Detroit Diesel Division General Motors are to be utilized to procure the high hard steel replacements.

To read:

In the event that plate replacement is necessary, only Detroit Diesel Division General Motors or its authorized supplier are to be utilized to procure the CMS 18 high hard steel replacements.

Change Paragraph 3.3.2.8 from:

At the induction stage of the vehicle, the contractor shall contact the Light Armored Vehicle Branch (832-1) in any case where the Single Channel Ground and Air Radio Set (SINCGARS) hardware is missing.

To read:

At the induction stage of the vehicle, the contractor shall contact the Communication Branch (Code C4I) in any case where the Single Channel Ground and Air Radio Set (SINCGARS) hardware is missing.

Change Paragraph 3.3.3.3 from:

The Marine Corps Logistics Bases (Code 832-1), PM-LAV, and/or their authorized representatives shall be permitted to observe the work and/or conduct inspections and perform testing during normal working hours.

To read:

The Marine Corps Logistics Bases (Code 832-1), PM-LAV, PM-MEWSS, and/or their authorized representatives shall be permitted to observe the work and/or conduct inspections and perform testing during normal working hours.

Change Paragraph 3.3.3.3.2

Failure to comply with any of the specified requirements listed within this SOW shall be reason for rejection by the (Code 832-1), PM-LAV, and/or their authorized representatives.

To read

Failure to comply with any of the specified requirements listed within this SOW shall be reason for rejection by the (Code 832-1), PM-LAV, PM-MEWSS, and/or their authorized representatives.

Change Paragraph 3.3.4.4 from:

Code 832-1 will provide FSD with the shipping address(es) for delivery of the repaired equipment. FSD shall be responsible for arranging for shipment to the PM-designated site(s). The Marine Corps will be responsible for transportation costs associated with shipping the equipment to and from FSD.

To read:

Code C4ISR will provide FSD with the shipping address(es) for delivery of the repaired equipment. FSD shall be responsible for arranging for shipment to the PM-designated site(s). The Marine corps will be responsible for transportation costs associated with shipping the equipment to and from FSD.

Change Paragraph 4.1.7 from:

The contractor shall develop a QAPP to be delivered 120 days after contract award to Code 832-1.

To read:


The contractor shall develop a QAPP to be delivered 120 days after contract award to Code 832-1 and Code C4ISR.

If approved, does this proposed change have the potential to have an impact on the cost or schedule?

* Yes / / or No / /

*Changes that have the potential to impact cost or schedule will be reviewed by Maintenance Directorate (MD) and an impact statement provided to LCMC. Changes that do not have the potential to impact cost or schedule may not be reviewed by MD.

Change Submitted by: Craig Harper 3 December 2001
Logistics Analyst
C4ISR (Code C4ISR)
MARCORSYSCOM, Albany GA

Change Approved by:  3 December 2001
William T Reynolds
Logistics Management Specialist
C4ISR (Code C4ISR)
MARCORSYSCOM, Albany, GA