Date: 4 March 2002

STATEMENT OF WORK
For the
Inspect and Repair Only As Necessary (IROAN)
Of the
Light Armored Vehicle (LAV-25)
Thermal Sight System
Processor Signal Data Circuit Card Assembly
NSN 5998-01-442-8178

SOW-04-PM-LAV-8H759B-2/1

1. No Statement Of Work (SOW) is required to IROAN the Processor Signal Data CCA, NSN 5998-01-442-8178, Part Number 6374508. The Marine Corps lack the necessary technical data for repair, and the technical data is proprietary to the Original Equipment Manufacturer (OEM). This is a commercially repaired item that has to be returned to the OEM.

2. The following points of contact apply:

Randy Geoghagan
Equipment Specialist
Program Manager
Light Armored Vehicles-Albany
MARCORSYSCOM, Albany, Ga.

Carolyn Mayberry
Inventory Management Specialist
Supply Chain Management Center
Combat Ground Weapons Branch Code 576-3
MARCORLOGBASES, Albany, Ga.