SOW CHANGE PROPOSAL

SOW-02-834-1-88653B –1/1 Change 1 26 Feb 2002

STATEMENT OF WORK (SOW)
for the
REBUILD
of the
AAV Circuit Card Assembly
NSN 5999-01-108-9786

SOW-02-834-1-88653B-1/1 Change 1

Change Paragraph 3.2.1.

Delete the last 3 sentences in the paragraph. A Rebuild Data Plate need not be fabricated and installed.

If approved, does this proposed change have the potential to have an impact on the cost or schedule?
* Yes /_/ or No /X/ (Place and X in the appropriate block)

*Changes that have the potential to impact cost or schedule will be reviewed by Maintenance Directorate (MD) and an impact statement provided to LCMC. Changes that do not have the potential to impact cost or schedule may not be reviewed by MD.

Change Submitted by: R. E. Hoffman 26 Feb 2002
Equipment Specialist
AFS-CTV/AAV
MARCORSYSCOM, Albany GA

Change Approved by R. E. Hoffman (Acting) 26 Feb 2002
Logistics Management Specialist
AFS-CTV/AAV
MARCORSYSCOM, Albany, GA

Change Disapproved by _____ (Name) _____Date
Logistics Management Specialist
_____ (Code _____)
MARCORSYSCOM, Albany, GA