SOW-02-847-1-08946A-1/1 Date: 4 April 2000

STATEMENT OF WORK
For the Repair of
Radio Set AN/VRC-83(V)2
NSN 5820-01-127-3485

This NSN is repaired by the lead service via DMISA. Statement of Work is not required.

WSEM POC: Mylan C. Hart,
FM/SATCOM Section (847-1)
Ground Communcations/Sensor Branch
C4I Division
DSN 567-6526/27
COM (912) 439-6526/27