| | | |
|---|---|---|
| SOW-01-834-1-88643C-1/1 | Change 1 | 25 Mar 02 |
| SOW-02-834-1-88643C-1/2 | Change 1 | 25 Mar 02 |
| SOW-03-834-1-88643C-1/1 | Change 1 | 25 Mar 02 |
| SOW-04-CBG-88643C-1/1 | Change 1 | 25 Mar 02 |

STATEMENT OF WORK (SOW)
for the
REBUILD
of the
AAV VT-400 Engine
NSN 2815-01-109-5052
And The
AAV VT-400 Engine With Container
NSN 2815-01-140-8799

**Change Paragraph 2.2 from:**

TM 88643B-45 Maintenance Instruction and Rebuild Standards.

**To read:**

TM 8F152B-25&P/A Maintenance Instructions and Repair Parts List Organizational, Intermediate and Depot Power Plant Assembly Assault Amphibious Vehicle 7A1 Family of Vehicles and RAM/RS

Remove TM 88643B-45 and Replace with TM8F152B-25&P/A where ever it appears throughout the SOW.

If approved, does this proposed change have the potential to have an impact on the cost or schedule?
Yes /_/ or No /X/

*Changes that have the potential to impact cost or schedule will be reviewed by Maintenance Directorate (MD) and an impact statement provided to LCMC. Changes that do not have the potential to impact cost or schedule may not be reviewed by MD.

Change Submitted by: Bob Hoffman 01/31/02
Sr. Equipment Specialist
AFS-CTV/AAV
MARCORSYSCOM, Albany GA

Change Approved by R E Hoffman (Acting) (Name) 03/25/02 Date
Logistics Management Specialist
AFS-CTV (Code AAV)
MARCORSYSCOM, Albany, GA

Change Disapproved by _____ (Name) _____ Date
Logistics Management Specialist
_____ (Code _____)
MARCORSYSCOM, Albany, GA