Date: 15 March 2002

STATEMENT OF WORK
For the
Inspect and Repair Only As Necessary (IROAN)
Of the
Light Armored Vehicle (LAV-25)
General Purpose Interface Assembly (GPIA)
Control Function Module
NSN 5998-01-383-3854

SOW-02-832-1-8G707B-2/1

1. No Statement Of Work is required to IROAN the Control Function Module, NSN 5998-01-383-3854, Part Number 92006A1200. The Marine Corps lack the necessary technical data to perform repair and the technical data is proprietary to the Original Equipment Manufacturer (OEM). This is a commercially repaired item that has to be returned to the PEI Electronics, Huntsville, Alabama via a MIMISA ACALA 99 01.

2. The following points of contact apply:

Randy Geoghagan
Equipment Specialist
Program Manager
Light Armored Vehicles-Albany
MARCORSYSCOM, Albany, Ga.

Blain Jolley
Inventory Management Specialist
Supply Chain Management Center
Combat Ground Weapons Branch Code 576-3
MARCORLOGBASES, Albany, Ga.