DATE: 1 Dec 00

STATEMENT OF WORK (SOW)
For the
Inspect and Repair Only As Necessary (IROAN)
of the
AN/TYQ-23(V)4
Bus Controller CCA
NSN: 5840-01-475-6654

SOW-04-C4I-8I303B-2/1

1. No Statement Of Work (SOW) is required to IROAN the AN/TYQ-23(V)4 Bus Controller CCA, NSN 5840-01-475-6654, part number 295786-100, CAGE 13973. This is a commercially repaired item.

2. The following points of contact apply:

HARVEY C. DEARING
Weapon System Equipment Manager
Data Systems Section (Code C4I)
MARCORSYSCOM, Albany, GA

NELLIE GARNER
Contracting Specialist
Contracting Branch (Code 891)
MARCORLOGBASES, Albany, GA

STEPHANIE D. BYRD
Team Leader
Inventory Management Specialist
(Code C4I)
MARCORSYSCOM, Albany, GA

ROBERT M. BARRY
Team Leader
Equipment Specialist
(Code C4I)
MARCORSYSCOM, Albany, GA