

# SOW CHANGE PROPOSAL

SOW-02-832-1-08652A-2/1, Change 2

7 August 2001

STATEMENT OF WORK (SOW)

For the

Inspection and Repair Only As Necessary (IROAN)

Of the

Light Armored Vehicle (LAV-AT)

NSN 2320-01-123-1609

SOW-02-832-1-08652A-2/1, Change 2

**Add new paragraph:**

3.3.2.9

**To read:**

3.3.2.9 Brake drums shall not exceed .036 inches (.912mm) above the standard measurement as outlined in TM 08594A 34/9A Paragraph 13-3. Those drums exceeding .036 (.912mm) must be replaced.

If approved, does this proposed change have the potential to have an impact on the cost or schedule?

\* Yes \_\_\_\_\_ No \_\_\_\_\_ (Place an X in the appropriate block)

\*Changes that have the potential to impact cost or schedule will be reviewed by Maintenance Directorate (MD) and an impact statement provided to LCMC. Changes that do not have the potential to impact cost or schedule may not be reviewed by MD.

Change Submitted by: SSA Joe J. B (Name) 7 Aug 01 Date

Equipment Specialist (Title)

(Code 552-1)  
MARCORSYSCOM, Albany, GA

Change Approved by Major Gen. Tuller (Name) 6 Oct 01 Date  
Logistics Management Specialist

(Code 551)  
MARCORSYSCOM, Albany, GA

Change Disapproved by \_\_\_\_\_ (Name) \_\_\_\_\_ Date  
Logistics Management Specialist

(Code \_\_\_\_\_)  
MARCORSYSCOM, Albany, GA