

SOW CHANGE PROPOSAL

SOW-02-833-4-07723C-1/1

Change 1

28 August 2001

STATEMENT OF WORK (SOW)
for the
DEPOT REBUILD
of the
TOW FIELD TEST SET, AN/TSM-140B
NSN 4935-01-173-5016

SOW Control Number (SOW-02-833-4-07723C-1/1) Change 1

1. Change Paragraph 4.1.b from: Using footnotes per the example in Appendix B, show the results, positive or negative, obtained related to previously identified problem areas, with conclusions and recommendations.


to read: Using footnotes to Appendix B, show the results, positive or negative, obtained related to previously identified problem areas, if any, with conclusions and recommendations.

2. Add: 4.1.m Report Identifier Code. Column "A" of the appendixes do not reflect a "Depot" Maintenance Identifier Code. Code DM is to be used to identify any Depot level maintenance performed.

If approved, does this proposed change have the potential to have an impact on the cost or schedule?

* Yes /_/ or No /X/ (Place and X in the appropriate block)

*Changes that have the potential to impact cost or schedule will be reviewed by Maintenance Directorate (MD) and an impact statement provided to LCMC. Changes that do not have the potential to impact cost or schedule may not be reviewed by MD.

Change Submitted by: 
Cejka, James E. (Name) 28 Aug 2001 Date
Equipment Specialist (Title)
Anti-Armor (Code 574-3)
MARCORLOGBASES, Albany GA

Change Approved by: 
Robert L. Walthall (Name) 28 Aug 2001 Date
Logistics Management Specialist
Anti-Armor (Code CBG-AA)
MARCORSYSCOM, Albany, GA

Change Disapproved by _____ (Name) _____ Date
Logistics Management Specialist

(Code _____)
MARCORSYSCOM, Albany, GA